Non-Clog Scroll Submersible Pump CNWX Example Application

Hogle Zoo Lift Station Salt Lake City, UT

Reduce Clogging Problem at Lift Station in UT



CNWX (3" Solid Size, 10HP) Our UT distributor has installed a lot of application since May 2010. They have never had clogging issue.

Apartment Lift Station El Monte, CA

Reduce Clogging Problem

Non-Clog Pump (2HP)		
Problem	Clogging Every Month	
Debris	Feminine sanitary product, Rag, etc.	





Retirement Home Lift Station Burlingame, CA



Reduce Clogging Problem

Non-Clog Pump (3" Solid Size, 2HP)			
Problem	Clogging Multiple Times per Week		
Debris	Diaper, Feminine sanitary product, Rag, etc.		



Non-Clog Scroll Submersible Pump CNWX Example Application

Lift Station, Plantation, FL

Replacement Application



This lift station experienced repeated clogging problems.

CNWX pump testing began in August 2012



Lift Station (Residential), Englewood, FL



This Lift Station had clogging problem every two weeks. No clogs since February 2013.



Lift Station (Prison), Camila, GA



This Lift Station had a frequent clogging problem. No Clogging problem since they began CNWX test in December 2012.



Non-Clog Scroll Submersible Pump CNWX Example Application

Lift Station and WWTP, Warner Robins, GA (4 Installations)



Reduce Clogging Problem

Competitor	Non-Clog	Pumps
------------	----------	-------

Problem Clogging frequently

Debris Rag, Feminine sanitary product, etc.







Lift Station, Tega Cay, SC (2 Installations)

Retro Fit Application



Our distributor in NC & SC has many successful CNWX installations similar to this.

No closs since May 2012.





Lift Station (Prison), Mauston, WI



